




## DAIWA CS201

### RIFERIMENTI


Genere	DATA	Generalità	Note	Distribuzione
radio	Jun 2014	Repair of switch cs120		Af web

### GENERALITA'

*This simple manual coaxial switch has been on duty a lot of time. Recently some problem has pop up. Mainly SWR.*



*Before to put it into the rubbish I've tried an inspection to see what was the real origin of the problem.*



*So I've found all three SO239 coax socket loose in the main body of switch, with a little backlash. Solution was to tighten the grain as in the picture above. The screw quality is not the best, as the off side cut in the grain shows in the right picture, albeit sufficient to work.*

*So, CS201 again on duty!*

*Buon divertimento, Alessandro Frezzotti*